

Statewide Survey of Historic Properties

Site Number: 326-0425

Survey Report for McClellanville

Tax Map No.: 764-14-00-108

Identification

Historic Name: Sarah Butler Doar House

Common Name: Prentiss House

Address/Location: 204 Charlotte Street

Ownership: Private

Category: Building

Historical Use: Domestic

Current Use: Domestic

National Register of Historic Places Information

SHPO National Regis DOE: Contributes to Listed District

Other Designation: contributes to a local district

Notes:

Property Description

Construction Date: c.1905

Historic Core Shape: rectangular

Stories: 2 1/2 stories

Construction Method: frame

Exterior Walls: weatherboard

Foundation: brick pier

Roof Features Shape: gable, lateral

Porch Features Porch Width: full facade

Materials: composition shingle

Shape: shed

Significant Architectural Features: two interior brick chimneys; two-story porch on south facade; 6/6 windows; three gabled dormers with 6/6 windows on north and south facades. First level entrance has transom and sidelights. Second level entrance has sidelights. Asbestos shingles at rear section. One-story rear gable kitchen wing attached by breezeway.

Alteration Date: 1989

Alterations: Kitchen breezeway infilled. Principal roof and porch roof replaced after Hurrican Hugo in 1989.

Photographs

Primary View:



Additional Views:



Date Recorded: 11/04/2007