

# Statewide Survey of Historic Properties

## Survey Report for McClellanville

Site Number: 326-0427.00

Tax Map No.: 764-14-00-106

### Identification

Historic Name: Louis Augustus Whilden House  
Common Name: Doar Cottage  
Address/Location: 125 Oak Street (127 Oak per Chas Co.)

Ownership: Private  
Historical Use: Domestic  
Category: Building  
Current Use: Domestic

### National Register of Historic Places Information

SHPO National Regis DOE: Contributes to Listed District  
Other Designation: contributes to a local district

Notes:

### Property Description

Construction Date: 1862  
Historic Core Shape: rectangular  
Stories: 1 1/2 stories  
Construction Method: frame  
Exterior Walls: other  
Foundation: brick pier

*Roof Features* Shape: gable, lateral  
*Porch Features* Porch Width: full facade  
Materials: raised seam metal  
Shape: shed

Significant Architectural Features: board and batten siding; 2 gabled dormers on north and south slopes with 6/6 windows and wide eaves; 2 exterior brick chimneys (east and west gable ends) with gothic caps; shed roof over side entry--east; 9/9 windows on first floor south elevation. Off-center four panel entry door.

Alteration Date: c. 1950; 1989;

Alterations: entry door altered--upper two panels removed and replaced with glass. Two single-story rear shed additions--last one c. 1950. Replacement foundation (1990); chimneys repointed/rebuilt after Hugo.

### Photographs

Primary View:



Additional Views:



Date Recorded: 1/28/2008