

Statewide Survey of Historic Properties

Site Number: 326-0428

Survey Report for McClellanville

Tax Map No.: 764-14-00-105

Identification

Historic Name: Rutledge Baker Leland House

Common Name:

Address/Location: 119 Oak Street

Ownership: Private

Category: Building

Historical Use: Domestic

Current Use: Domestic

National Register of Historic Places Information

SHPO National Regis DOE: Contributes to Listed District

Other Designation: contributes to a local district

Notes:

Property Description

Construction Date: c. 1916

Historic Core Shape: rectangular

Stories: 1 1/2 stories

Construction Method: frame

Exterior Walls: weatherboard

Foundation: brick pier

Roof Features Shape: hip

Porch Features Porch Width: entrance bay only

Materials: raised seam metal

Shape: hip

Significant Architectural Features: One-story hip porch on east elevation. Hipped dormer at rear with band of three double light windows. Hip wing at west elevation. (1992 survey). Eaves slightly flared. One interior brick chimney. Single-story entry porch supported by tapered square columns.

Alteration Date: c. 1980 & 1989

Alterations: Windows replaced since 1992 survey. Per 1992 survey rear porch enclosed; hipped addition at north elevation; foundation and chimney rebuilt/restuccoed post Hugo.

Photographs

Primary View:



Additional Views:



Date Recorded: 11/04/2007